

AEROSPACE INFORMATION REPORT

SAE AIR811

REV.
B

Issued 1965-01
Revised 1996-04
Reaffirmed 2001-11

Superseding AIR811A

Disposition of Wheels Which Have Been Overheated

INTRODUCTION

The development and use of brakes with high temperature capabilities has resulted in instances of tire and wheel failures which were attributed to excessive brake heat. These instances have led to the establishment of more stringent wheel requirements and the addition of heat shields, safety devices, auxiliary cooling devices, brake temperature, and low tire pressure indication systems.

1. SCOPE:

This SAE Aerospace Information Report (AIR) has been prepared to assist those who are concerned with the removal, inspection, and disposition of magnesium and aluminum wheels which may have been subjected to excessive temperatures.

2. REFERENCES:

There are no referenced publications specified herein.

3. MAGNESIUM AND ALUMINUM WHEEL MATERIALS:

The effect of temperature and heating time on the mechanical properties of a material is a unique function of the material being used. It is, therefore, necessary that the wheel manufacturer supply the user with information as to how to detect wheel degradation due to excessive temperature as well as dimensional limits for the wheel. The wheel manufacturer should supply the user with nondestructive test methods and acceptance standard suitable for making proper part disposition.

4. REMOVING WHEELS FROM THE AIRCRAFT FOR INSPECTION:

4.1 Temperature Limitation:

If evidence exists, or if it is suspected that the wheel has been heated to temperatures in excess of the limit established, the wheel(s) should be removed from service for inspection.

SAE Technical Standards Board Rules provide that: "This report is published by SAE to advance the state of technical and engineering sciences. The use of this report is entirely voluntary, and its applicability and suitability for any particular use, including any patent infringement arising therefrom, is the sole responsibility of the user."

SAE reviews each technical report at least every five years at which time it may be reaffirmed, revised, or cancelled. SAE invites your written comments and suggestions.

Copyright 2001 Society of Automotive Engineers, Inc.
All rights reserved.

Printed in U.S.A.

TO PLACE A DOCUMENT ORDER: (724) 776-4970

FAX: (724) 776-0790

SAE WEB ADDRESS: <http://www.sae.org>

SAE AIR811 Revision B

4.2 Evidence of Excessive Temperatures:

- 4.2.1 When a temperature sensitive pressure release device (fuse plug) has functioned or is found partially melted as evidenced by tire deflation or wheel inspection.
- 4.2.2 When a tire shows evidence of having been subjected to excessive temperature on side walls outside of the wheel flanges.
- 4.2.3 When the paint on the wheel has become discolored and/or blistered.

5. GENERAL NOTES:

- 5.1 Item 4.2.1 is not indicative of the actual temperature which may have been experienced by the wheel. The brake can continue to raise the wheel temperature after the air has been released.
- 5.2 As temperature increases, the resistance to creep and permanent yielding decreases. It is, therefore, possible that a wheel can be permanently deformed by a combination of aircraft weight, heat, and tire deflation.
- 5.3 Document evidence of excessive temperatures. Note location, degree, and details of part condition for reference use.

6. INSPECTION PROCEDURE:

- 6.1 Demount the tire, remove wheel seals, and thoroughly clean wheel halves per wheel manufacturer's instructions.
- 6.2 Remove only sufficient paint (if applicable) and anodic treatment from areas of wheel halves designated by wheel manufacturer to permit the following nondestructive tests to be performed.
- 6.3 Inspect the wheel as follows
 - a. Perform evaluation tests on the wheel using Method I and/or Method II as follows:
 - 1. Method I - Conductivity Test (Eddy Current):
 - (a) Perform conductivity test in designated areas of wheel according to specified procedures of wheel manufacturer.

CAUTION: In performing conductivity tests, it is important to use test equipment and acceptance values approved by the wheel manufacturer. These values may require adjustment if alternative test equipment is used.
 - (b) Wheels which fail to pass this test may be subjected to the Method II test as a final hardness rejection criteria.